ERROR CODES




Error No. 53

AWARNING

Please refer to the Safety Precautions on pages 4-7 for more detail to prevent injury or death regarding the operation and service troubleshooting of the Multi V product.

Error No. Description		Details	Causes	
53 Master: 531 Slave 1: 532 Slave 2: 533	Communication error between outdoor unit main PCB and indoor unit (s) PCB.	Outdoor unit main PCB cannot receive the signal from the indoor unit.	 Communication cables are not connected between external PCB and indoor PCB. Communications cables are disconnected or have short circuited between the main PCB and external PCB. Communication cables are disconnected or have short circuited between the main PCB and communication PCB. Communication cables are disconnected or have short circuited (communication cable connection error.) Power to the indoor PCB is off. Defective outdoor unit main PCB, communication PCB, and / or indoor unit PCB. Outdoor unit main PCB / indoor unit PCB is defective or damaged. 	





ERROR CODES

Error No. 53, continued.

AWARNING

Please refer to the Safety Precautions on pages 4-7 for more detail to prevent injury or death regarding the operation and service troubleshooting of the Multi V product.

Error No. 53 indicates there is a communication error between the outdoor unit and indoor unit(s). See LGMV to help determine which indoor unit or units are not communicating with the outdoor unit.


- Does LGMV display the correct number of indoor units? If LGMV DOES NOT display the correct number of indoor units, find the missing indoor unit or units and troubleshoot.
- If LGMV DOES displays the correct number of indoor units, but the outdoor unit still shows CH53, check the communication count line on LGMV. Find the indoor unit that does not have a communication count increase—that indicates the indoor unit which is not communicating. The indoor unit may have:
- 1. Wrong communication cable or power wiring connection(s).
- 2. A PCB malfunction.
- 3. Duplicate address numbers for indoor units (Error No. 53 will appear at the indoor unit).

LGMV Communication Line Example

IDU Gr.1			More HR Info		nfo	More Idu Info		
	comm.	CEN	error	humidity	H/L	TGT	TGT2	
IDU1	38	6	0	0	0	0	0	
IDU2	39	2	0	0	0	0	0	
IDU3	38	8	0	0	0	0	0	
IDU4	37	1	0	0	0	0	0	
IDU5	37	0	0	0	0	0	0	
IDU6	37	5	0	0	0	0	0	
IDU7	38	7	0	0	0	0	0	
IDU8	38	4	0	0	0	0	0	

Note:

- If communication in general is not functioning properly, then the auto addressing procedure has not been performed yet or has not been performed properly.
- Auto addressing must be performed after an indoor unit PCB has been replaced. Also, if a central controller is installed, the central controller address must be input.
- In addition to the information presented here, see also the troubleshooting procedure for Error No. 05.





Note:

Images here are representative of system components. Actual component appearance depends on model and system type.

