

⚠ WARNING Please refer to the Safety Precautions on pages 4-7 for more detail to prevent injury or death regarding the operation and service troubleshooting of the Multi V product.

Error No.	Description	Details	Causes
25	Input voltage to the outdoor unit is too high or too low.	Outdoor unit has an input voltage of <140V or >300V.	1. Input voltage is abnormal. 2. Outdoor unit inverter PCB assembly is damaged (input voltage sensor component). 3. A phase line is disconnected.

